

# AIR TEMPERATURE AND DEW POINT TEMPERATURES (FAHRENHEIT)

20 30 40 50 60 70 80 90 100 110

WET BULB DEPRESSION  
(DIFFERENCE BETWEEN WET AND DRY BULB TEMPERATURES)

35  
30  
25  
20  
15  
10  
5

RELATIVE HUMIDITY (%)

20  
30  
40  
50  
60  
70  
80  
90

2 3 4 5 6 7 8 9 10 12 14 16 18 20 22 24

ABSOLUTE HUMIDITY (GRAINS OF H2O PER CUBIC FT.)

